

Division of Licensing and Protection
HC 2 South, 280 State Drive
Waterbury VT 05671-2060
<http://www.dail.vermont.gov>
Survey and Certification Voice/TTY (802) 241-0480
Survey and Certification Fax (802) 241-0343
Survey and Certification Reporting Line: (888) 700-5330
To Report Adult Abuse: (800) 564-1612

January 27, 2022

Mr. Bradford Ellis, Administrator
Vernon Green Nursing Home
61 Greenway Drive
Vernon, VT 05354-9474

Provider #: 475008

Dear Mr. Ellis:

Enclosed is a copy of your acceptable plans of correction for the **Life Safety Code survey** conducted on **October 29, 2021**. Please post this document in a prominent place in your facility.

We will follow-up to verify that substantial compliance has been achieved and maintained. If we find that your facility has failed to achieve or maintain substantial compliance, remedies may be imposed.

Sincerely,



Pamela M. Cota, RN
Licensing Chief

Enclosure

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 475008	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 10/29/2021
NAME OF PROVIDER OR SUPPLIER VERNON GREEN NURSING HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 61 GREENWAY DRIVE VERNON, VT 05354		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 362	<p>Continued From page 1</p> <ol style="list-style-type: none"> 1. Per observation on October 29, 2021, and accompanied by the Director of Environmental Services, inspection revealed there is a penetration in the wall in the B-Wing Housekeeping closet. 2. Per observation on October 29, 2021, and accompanied by the Director of Environmental Services, inspection revealed that the B-Wing Med room has a penetration in the ceiling next to the light. 3. Per observation on October 29, 2021, and accompanied by the Director of Environmental Services, inspection revealed that the B-Wing Air Handler room ceiling has penetration around pipes. 4. Per observation on October 29, 2021, and accompanied by the Director of Environmental Services, inspection revealed that the A-Wing IT room has penetrations around electrical receptacles. 5. Per observation on October 29, 2021, and accompanied by the Director of Environmental Services, inspection revealed that the A-Wing Old Handler room has penetrations in the ceiling and walls. 6. Per observation on October 29, 2021, and accompanied by the Director of Environmental Services, inspection revealed in the A-Wing Hallway to the loading dock there are penetrations in the walls. 7. Per observation on October 29, 2021, and accompanied by the Director of Environmental Services, inspection revealed that the acoustical 	K 362			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 475008	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 10/29/2021
NAME OF PROVIDER OR SUPPLIER VERNON GREEN NURSING HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 61 GREENWAY DRIVE VERNON, VT 05354		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 363	Continued From page 3 window assemblies are allowed per 8.3. In sprinklered compartments there are no restrictions in area or fire resistance of glass or frames in window assemblies. 19.3.6.3, 42 CFR Parts 403, 418, 460, 482, 483, and 485 Show in REMARKS details of doors such as fire protection ratings, automatics closing devices, etc. This REQUIREMENT is not met as evidenced by: Per observation on October 29, 2021, the facility failed to ensure no impediment when closing doors. Findings include the following: 1. Per observation on October 29, 2021, and accompanied by the Director of Environmental Services, inspection revealed the door to Room 205 in the B-Wing does not lock and latch. 2. Per observation on October 29, 2021, and accompanied by the Director of Environmental Services, inspection revealed the Clean Serviceroom in the A-Wing does not lock and latch. 3. Per observation on October 29, 2021, and accompanied by the Director of Environmental Services, inspection revealed the door to the Rehabilitation room in the A-Wing was held open by a doorstop.	K 363			
K 500 SS=D	Building Services - Other CFR(s): NFPA 101 Building Services - Other List in the REMARKS section any LSC Section 18.5 and 19.5 Building Services requirements that	K 500	Beginning on page 5		

