

## DEPARTMENT OF DISABILITIES, AGING AND INDEPENDENT LIVING

<u>Division of Licensing and Protection</u> HC 2 South, 280 State Drive

Waterbury, VT 05671-2060

http://www.dail.vermont.gov

Survey and Certification Voice/TTY (802) 241-0480

Survey and Certification Fax (802) 241-0343

Survey and Certification Reporting Line: (888) 700-5330

To Report Adult Abuse: (800) 564-1612

July 27, 2023

Mr. Chadd Viger, Manager Serenity House Po Box 207 Wallingford, VT 05773-0207

Dear Mr. Viger:

Enclosed is a copy of your acceptable plans of correction for the survey conducted on **July 17**, **2023.** Please post this document in a prominent place in your facility.

We may follow up to verify that substantial compliance has been achieved and maintained. If we find that your facility has failed to achieve or maintain substantial compliance, remedies may be imposed.

Sincerely,

Pamela M. Cota, RN

Lamela M CotaRN

Licensing Chief

Division of Licensing and Protection

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY COMPLETED	
			A. BUILDING:		C	
0524		B. WING		07/17/2023		
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE						
SERENITY HOUSE PO BOX 207						
WALLINGFORD, VT 05773  (X4) ID SUMMARY STATEMENT OF DEFICIENCIES ID PROVIDER'S PLAN OF CORRECTION (X5)						
(X4) ID PREFIX TAG	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	(EACH CORRECTIVE ACTION SHOULD	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE	
T 001	1 Initial Comments		T 001			
	conjunction with two conducted by the Divi	. The following regulatory				
T 174 SS=F	IX.9.6.d Physical Plant		T 174	In reference to deficiency T174, F House has the following response		
	9.6 Plumbing			On 7/17/23, Recovery House imm	nediately	
	9.6.d Hot water temperatures shall not exceed 120 degrees Fahrenheit in resident areas			responded to the water temperatures by turning down the thermostat of the water heater.		
	by: Based on observation was a failure to ensur not exceed 120 degree	is not met as evidenced and staff interview there e water temperatures did eses Fahrenheit in resident utic Community Residence de:		As a future preventative measure Recovery House will further train educate the facilities manager. The facilities manager will audit the way monthly, to ensure correct temper The Operations Coordinator will ethis is done routinely.	and ne ater temp ratures.	
	temperatures exceed degrees Fahrenheit in Resident restroom #1 water temperature wa degrees Fahrenheit, a located on the second was noted to be 126.4	located on the second-floor		Tag T174 accepted on 07-27-2023 S. Ross RN	3	
				Chadd Viger CEO		7/27/23

Division of Licensing and Protection LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

(X6) DATE TITLE