

## DEPARTMENT OF DISABILITIES, AGING AND INDEPENDENT LIVING

Division of Licensing and Protection
HC 2 South, 280 State Drive
Waterbury VT 05671-2060
<a href="http://www.dail.vermont.gov">http://www.dail.vermont.gov</a>
Survey and Certification Voice/TTY (802) 241-0480
Survey and Certification Fax (802) 241-0343
Survey and Certification Reporting Line (888) 700-5330
To Report Adult Abuse: (800) 564-1612

May 16, 2019

Mr. Allen Yearick, Administrator Woodridge Nursing Home P.O. Box 550 Barre, VT 05641-0550

Provider ID #: 475045

Dear Mr. Yearick:

The Department of Public Safety, Division of Fire Safety completed a Life Safety Code survey at your facility on May 13, 2019. The purpose of the survey was to determine if your facility was in compliance with Federal participation requirements for nursing homes participating in the Medicare and Medicaid programs. This survey found that your facility was in substantial compliance with the participation requirements. However, there is one deficiency that does not require a plan of correction but does require a commitment to correct. All references to regulatory requirements contained in this letter are found in Title 42, Code of Federal Regulations. Please sign the enclosed CMS-2567 and return the original to this office by May 26, 2019.

## Informal Dispute Resolution

In accordance with §488.331, you have one opportunity to question cited deficiencies through an informal dispute resolution process. To be given such an opportunity, you are required to send your written request, along with the specific deficiencies being disputed, and an explanation of why you are disputing those deficiencies, to Suzanne Leavitt, RN, MS, Assistant Division Director, Division of Licensing and Protection. This request must be sent during the same ten days you have for returning the enclosed CMS-2567 statement of deficiencies. An incomplete informal dispute resolution process will not delay the effective date of any enforcement action.

Sincerely,

Pamela Cota RN Licensing Chief

PamlaMCHaRN

## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: -05/16/2019 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION  A. BUILDING 01 - MAIN BUILDING 01					(X3) DATE SURVEY COMPLETED		
475045					·	05/13/2019					
NAME OF PROVIDER OR SUPPLIER  WOODRIDGE NURSING HOME					P.O. BOX BARRE,	ZIP CODE					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG		PROVIDE (EACH CORI ROSS-REFEI	D BE	(X5) COMPLETION DATE			
K 000	INITIAL COMMEN	TS	-	K 0	00	×	*				
	An unannounced inspection was con Safety on 05/13/19 to be in substantial issues were identifiate facility.	mpleted by the Div D. While the facility I compliance, the	vision of Fire v was found following						8		
	· · · · · · · · · · · · · · · · · · ·										
ADODATOS	V DIRECTOR'S OR PROVI	DEDICHDRUS SESS	TOPMTATIVE CO	NATURE			TI E			(X6) DATE	

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

ATEMENT OF	ISOLATED DEFICIENCIES WHICH CAUSE	PROVIDER #	MULTIPLE CONSTRUCTION	DATE SURVEY						
	ONLY A POTENTIAL FOR MINIMAL HARM		A. BUILDING: 01 - MAIN BUILDING 01	COMPLETE:						
R SNFs AND 1	NI 5	475045	B. WING	5/13/2019						
NAME OF PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP CODE P.O. BOX 550								
OODRIDG	EE NURSING HOME	BARRE, VT								
EFIX G	SUMMARY STATEMENT OF DEFICIE	ENCIES								
363	Corridor - Doors CFR(s): NFPA 101		E T							
	Corridor - Doors Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas resist the passage of smoke and are made of 1 3/4 inch solid-bonded core wood or other material capable of resisting fire for at least 20 minutes. Doors in fully sprinklered smoke compartments are only required to resist the passage of smoke. Corridor doors and doors to rooms containing flammable or combustible materials have positive latching hardware. Roller latches are prohibited by CMS regulation. These requirements do not apply to auxiliary spaces that do not contain flammable or combustible material. Clearance between bottom of door and floor covering is not exceeding 1 inch. Powered doors complying with 7.2.1.9 are permissible if provided with a device capable of keeping the door closed when a force of 5 lbf is applied. There is no impediment to the closing of the doors. Hold open devices that release when the door is pushed or pulled are permitted. Nonrated protective plates of unlimited height are permitted. Dutch doors meeting 19.3.6.3.6 are permitted. Door frames shall be labeled and made of steel or other materials in compliance with 8.3, unless the smoke compartment is sprinklered. Fixed fire window assemblies are allowed per 8.3. In sprinklered compartments there are no restrictions in area or fire resistance of glass or frames in window assemblies.									
	19.3.6.3, 42 CFR Parts 403, 418, 460, 482, 483, and 485 Show in REMARKS details of doors such as fire protection ratings, automatics closing devices, etc. This REQUIREMENT is not met as evidenced by: Based on observation, the facility failed to ensure that the clearance between bottom of the door and floor covering does not exceed one inch and that there is no impediment to the closing of the doors.									
	Per observation on 5/13/19, accompanied by the facility physical plant manager, rooms with patients that have an infectious issue had two hooks placed over the top of the door to hold Personal Protective Equipment. In addition, one of the doors on the Evergreen Unit had significant rubbing on the top of the door frame which creates an impedance.									
	Į.									
		e.								
		*								
	•									
		*								

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of

The above isolated deficiencies pose no actual harm to the residents